

CHECKLIST FOR N

BEFORE STARTING

1. WALK AROUND INSPECTION
2. CHECK FUEL AND CAP
3. CHECK OIL
4. CHOCK NOSE GEAR - 1" WOOD BLOCK

STARTING

1. FUEL VALVE ON

2. MIXTURE RICH
3. CARB HEAT OFF
- 4. MAGS OFF**
5. PRIME 3 TIMES
6. STAND BETW. WING AND PROP - 4 BLADES
7. MAGS ON BOTH
8. THROTTLE CRACKED
9. START - OIL PRESS. IN GREEN W/IN 30 SEC.

Oil press. @ min. idle 10; norm. run-up 30 to 35 PSI

BEFORE TAKE-OFF

1. RUN-UP AT 1800 RPM
2. CHECK MAGUS - MAX MAG DROP = 125 RPM
3. CHECK CARB HEAT
4. CHECK INSTRUMENTS AND RADIO
5. CHECK CONTROLS
6. TRIM NEUTRAL

BEFORE LANDING

1. MIXTURE RICH
2. CARB HEAT ON
3. GEAR DOWN
4. FLAPS BELOW 95 MPH
5. APPROACH AT 60 MPH

AIRCRAFT SHUTDOWN

1. RADIO OFF
2. VSI OFF
3. PULL MIXTURE FULL LEAN
4. MAGUS OFF
5. RADIO MASTER OFF
6. FUEL VALVE OFF